Circa 1924

The Clarence V. Burch House which now stands unoccupied and suffers from neglect, is a typical example of a very common Charles County house form during the first quarter of the twentieth century, the center gable I-house. Two stories high and one room deep, this dwelling also includes the frequently found one story hipped roof porch on the facade and a kitchen dependency extending from the rear to create an L-plan. Although several additions have extended the rear elevations, the essential form remains intact with minimal loss of original materials.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. CH-611

1. Name of I	Property	(indicate prefer	ed name)			
historic	Clarenc	e V. Burch House				
other						
2. Location	***************************************					
street and number	12580 N	ed's Place			not for pu	ublication
city, town	Waldorf				x vicinity	
county	Charles					
3. Owner of	Property	(give names and ma	iling addresses of a	all owners)		
name	Joseph	Burch, et al				
street and number	P.O. Bo	P.O. Box 548		tel	lephone Un	known
city, town	Waldorf		state	MD zip	code 206	504-0548
4. Location	of Legal [Description				
courthouse, registr	y of deeds, etc.	Charles County		tax map	and parcel: 1	6-1-112
city, town	LaPlata			liber	1051 folio	425
Contributing Re Determined Eliq Determined Ine Recorded by H.	esource in Local gible for the Natio eligible for the Na ABS/HAER	al Register District Historic District onal Register/Maryland Ro tional Register/Maryland I earch Report at MHT	-			
6. Classifica	ition					
Category district building(s) structure site object	Ownership public private both	Current Function x agriculture commerce/trade defense domestic education funerary government health care industry	landscape recreation/cult religion social transportation work in progre unknown vacant/not in u	Contril ture 1 2 2 2 2 2 2 2 2 3 3 3 4 5 5 5 5 6 7 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	2 2 3 2	objects Total

7. Description		Inventory No. CH-611			
Condition					
excellent	x deteriorated				
good	ruins				
— fair	altered				

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The Clarence V. Burch House, built circa 1925 is located on a 42 acre farm off of Poplar Hill Road in the northern part of Charles County near Waldorf. The principal dwelling and associated outbuildings are clustered in an area of approximately four acres. The dwelling consists of a late 19th century I-house with a center gable and a two story kitchen wing joined by several later additions. Outbuildings include a tobacco barn, corncrib and two sheds. The site is approached by a dirt driveway that circles the dwelling and then converges to form a single-lane drive to the outbuildings located behind the house.

The Clarence V. Burch House is a two story, three bay frame structure currently clad in asbestos shingles. The steeply pitched roof is currently covered in asphalt shingles. A one story, hipped roof porch addition extends the 3/4 length of the façade. The main section of the structure is single pile. Only the second story windows were visible at the time of the survey which consists of 6/6 lights wood sash double-hung windows. A fan-shaped lunette window is found in the center gable.

The eastern elevation shows evidence of several building periods. A possibly original kitchen wing is visible at the northern end of the rear elevation creating a common L-plan. A later two story shed addition was extended from the southern elevation to meet the existing gable wall. At least three later additions are also visible on the southern elevation including a two story extension of the kitchen wing to join the original south wall, and two later one story shed additions.

Currently the Richard A. Burch House is unoccupied and suffers from neglect. Although the dwelling has undergone several later additions a good deal of the original character remains intact. The façade and northern elevation which are first visible when approaching the dwelling, retain a large portion of their historic appearance.

OUTBUILDINGS

The outbuildings located on the site included two contributing structures consisting of a tobacco barn and corncrib. The tobacco barn is clad with vertical boards and includes a shed addition on the southern elevation. The roof ridge runs on a east/west axis.

The corncrib is located to the southwest of the barn. It is clad with vertical slats and spaced to allow air circulation throughout. The roof ridge runs on a north/south axis. Both structures show signs of deterioration and loss of original materials.

8. Significan	ice		Inve	entory No. CH-611	
Period Are	as of Significance agriculture archeology architecture art commerce communications community planning conservation	Check and justify be economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement	elow	health/medicine industry invention landscape architecture law literature maritime history military	performing arts philosophy politics/government religion science social history transportation other:
Specific dates	Circa 1925		Architect	unknown	
Construction dates	Circa 1925		Builder	Unknown	
Evaluation for:					
National F	Register	Maryland Reg	gister	x not e	evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance reports, complete evaluation on a DOE Form - see manual.)

The Clarence V. Burch House is a good example of the continuing popularity of the center gable I-house in vernacular building traditions throughout the region. This particular form was an extremely popular building plan associated with farm families throughout Charles County from the third quarter of the nineteenth century until the second quarter of the twentieth century. Common characteristics include a single pile, two-story, three bay composition, centered gable, and a one story full length porch. Open fields and several outbuildings including a tobacco barn and corncrib located behind the house, contribute to the site's overall significance by providing an appropriate, authentic setting for this rural resource.

The dwelling and property have been in the Burch family for over one hundred years. In 1881 James M. Burch sold to Richard A. Burch approximately 42 acres of land. Richard, in turn, sold the same to Clarence Vernon Burch in 1924, who likely built the current dwelling shortly after the purchase. Joseph Louis Burch inherited the property which later passed to his heirs. In 1995 it was sold to Charles County Sand & Gravel.

Although deteriorated, the Burch House retains a great deal of its original historic character. The façade remains intact and no significant development has disturbed the immediate surrounding landscape.

9. Major Bibliographical References

Inventory No. CH-611

10. Geographical Data

Acreage of surveyed property

41.743

Acreage of historical setting

4

Quadrangle name

Hughesville

Quadrangle scale

1:24,000

Verbal boundary description and justification

The property at 12580 Ned's Place is and has been historically associated with Charles County Property Map 16, Grid 1, Parcel 112.

11. Form Prepared By

name/title	Cathy Currey/Historic Site Surveyor		
organization	Charles County Planning Department	date	9/4/2000
street and number	200 Baltimore Street	telephone	301-396-581
city or town	LaPlata	state MD	zipcode 20646

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

DHCD/DHCP

100 Community Place Crownsville MD 21032

410-514-7600

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. CH-611

Section 8 Page 1	Clarence V. Burch House
	name of property
	Charles County, MD
	county and state

Chain of title:

September 15, 1881

James M. Burch to Richard A. Burch. No acreage mentioned.

B.G.A. 5 Folio 325

March 28, 1924

Richard A. Burch, single to Clarence Vernon Burch. Buildings and

improvements. No acreage mentioned.

W.M.A. 42 Folio 8

January 29, 1985

Russell A. Burch and Joseph Louis Burch for Haddie Burch

(mother), widow of Clarence Vernon Burch to above. See Orphans

Court No. 6580.

Liber 1048 Folio 95

February 19, 1985

Joseph Louis Burch to Joseph Louis Burch and Christine H. Burch.

Improvements assessed 08-011095.

Liber 1051 Folio 425

MARYLAND INVENTORY OF HISTORIC PROPERTIES CONTINUATION SHEET

Inventory No. CH-611

Section 9 Page 1

Clarence V. Burch House name of property Charles County, Maryland county and state


Major Bibliographic References:

Brown, Jack D., et al. *Charles County, Maryland, A History*. Charles County Bicentennial Committee, 1976.

Charles County Land Records, Charles County Courthouse, LaPlata, Maryland.

Klapthor, Margaret Brown. *The History of Charles County, Maryland*. LaPlata, MD: Charles County Tercentenary, Inc., 1958.

Name: CLARENCE V. BURCH HOUSE RESOURCE SKETCH MAP
Date: 11/18/99 Ned's Place Address:__ CH- 611 North arrow Charles County, Maryland
Waldorf V 4 ✓ Vicinity Barn Cornerib cultivated field Not drawn to scale



Clarence V. Burch House CH-611 Charles County, MD LaPlata Quad



CH-611 DWELLING, 12580 NEDS PLACE CHARLES COUNTY, MD. K.G. SMITH

MARYLAND SHOO WEST ELEVATION



CH-611

DWELLING, 12580 NED'S PLACE

CHARLES COUNTY, MD

K.G. SMITH

III/99

MARYLAND SHOO

LOOKING NORTH WEST

2053



CH-611
DWELLING, 12580 NED'S PLACE
CHARLES COUNTY, MD

K. G. SMITH
1199
MARRYLAND SHPO
BARN & CORNCRIB, LOOKING EAST
3 OF 3